


Upínač pro frézy se závitem



Název	Kužel	M	D	d ₂	d ₁	L	A	G 2,5 25.000 min ⁻¹
HSK63A.51.M.06	HSK63A	6	13	10	6,5	25	51	•
HSK63A.51.M.08	HSK63A	8	15	13	8,5	25	51	•
HSK63A.76.M.08	HSK63A	8	23	13	8,5	50	76	•
HSK63A.101.M.08	HSK63A	8	23	13	8,5	75	101	•
HSK63A.51.M.10	HSK63A	10	20	18	10,5	25	51	•
HSK63A.76.M.10	HSK63A	10	23	18	10,5	50	76	•
HSK63A.126.M.10	HSK63A	10	32	18	10,5	100	126	•
HSK63A.176.M.10	HSK63A	10	37	18	10,5	150	176	•
HSK63A.51.M.12	HSK63A	12	24	21	12,5	25	51	•
HSK63A.76.M.12	HSK63A	12	24	21	12,5	50	76	•
HSK63A.101.M.12	HSK63A	12	31	21	12,5	75	101	•
HSK63A.126.M.12	HSK63A	12	33	21	12,5	100	126	•
HSK63A.176.M.12	HSK63A	12	40	21	12,5	150	176	•
HSK63A.51.M.16	HSK63A	16	29	29	17	25	51	•
HSK63A.76.M.16	HSK63A	16	34	29	17	50	76	•
HSK63A.101.M.16	HSK63A	16	34	29	17	75	101	•
HSK63A.126.M.16	HSK63A	16	36	29	17	100	126	•
HSK63A.176.M.16	HSK63A	16	43	29	17	150	176	•
HSK100A.79.M.08	HSK100A	8	23	13	8,5	50	79	•
HSK100A.79.M.10	HSK100A	10	23	18	10,5	50	79	•
HSK100A.129.M.10	HSK100A	10	32	18	10,5	100	129	•
HSK100A.179.M.10	HSK100A	10	37	18	10,5	150	179	•
HSK100A.79.M.12	HSK100A	12	24	21	12,5	50	79	•
HSK100A.129.M.12	HSK100A	12	33	21	12,5	100	129	•
HSK100A.179.M.12	HSK100A	12	40	21	12,5	150	179	•
HSK100A.79.M.16	HSK100A	16	34	29	17	50	79	•
HSK100A.129.M.16	HSK100A	16	36	29	17	100	129	•
HSK100A.179.M.16	HSK100A	16	43	29	17	150	179	•

Doporučené utahovací momenty

M6	10 Nm
M8	25 Nm
M10	40 Nm
M12	50 Nm
M16	60 Nm